RS01W-17

1202

Date:

INSPECTION

HINT:

The SRS wire harness is integrated with the instrument panel wire harness assembly. All the connectors in the system are a standard yellow color.

1. VEHICLE NOT INVOLVED IN COLLISION

Do a diagnostic system check. (See page DI-239)

2. VEHICLE INVOLVED IN COLLISION

- (a) Do a diagnostic system check. (See page DI-239)
- (b) Check breaks in all wires of the SRS wire harness, and exposed conductors.
- (c) Check to see if the SRS wire harness connectors are cracked or chipped.

Author:

2002 ECHO (RM884U)